

TT 520 . G57











A COURSE OF STUDY IN WOMEN'S GARMENT DESIGN FOR

VOCATIONAL AND CONTINUATION SCHOOLS

BY

AARON GLICKSTEIN

INSTRUCTOR, EAST NEW YORK CONTINUATION SCHOOL

39 LESSONS

COPYRIGHT, 1924 BY AARON GLICKSTEIN
1349-49 STREET
BROOKLYH, N.Y.

TT520 G57

etis .

OCIA802578

1 24322284

mo (

JOB No. 1-a

e. A SURVEY b. TAKING LEASUREMENTS

SURVEY.

FROM THE STANDPOINT OF THE NUMBER OF PROPLE EMPLOYED AND THE CAPITAL INVESTED, THE WOMEN'S GARMENT INDUSTRY RANKS AMONG THE MOST IMPORTANT NOT ONLY OF NEW YORK BUT OF THE ENTIRE WORLD.

MEEN OBSERVATION, ABILITY TO FOLLOW INSTRUCTIONS, SKILL FITH FIGURES, ACCURACY, SPEED, HEATNESS AND ADAPTABILITY ARE NECESSARY QUALIFICATIONS FOR SUCCESS.

JOBS AS TRRAND BOYS, CLOTH BUNDLERS, HELPERS, SHIPPING CLERKS OR OFFICE HELP ARE OFFERED AS STARTERS TO THE BOYS THO ENTER THIS INDUSTRY.


THE DESIGNER IS THE HIGHEST PAID FORKER. HE DESIGNS AND PLANS THE GARMENT.

THE CUTTER MUST KNOW HOW TO MAKE ECONOMICAL LAYOUTS.

OF ALL THE OCCUPATIONS IN THE GARMENT TRADE THESE TWO (designer, cutter) ARE THE MOST INVITING TO THE AMERICAN BOY.

THE TRADE MAY BE DIVIDED INTO THREE BRANCHES; viz., DESIGNING, CUTTING AND TAILORING OR SEWING.

THE FOLLOWING OPPORTUNITY CHART INDICATES THE MAIN DIVISIONS OF WORK.





WOMEN'S GARMENT DESIGN

Job No. 1-b
Taking Measurements for a Skirt

For what purpose do me measure a figure?

We take measurements in order so draft a pattern

er a garment. The cloth is cut according to the

pattern. Then the various pieces of cut cloth are sewed

Take a tope measure and pencil and measure the

figure as shown on the illustration below.

On a sheet of paper write the name and number of inches of each measurement.

Example: Waist - 29" (Prepresents inches)

Hips - 41" Side Length - 41"

Front Length - 40" Back Length - 41"





WOMERS GARGINAT DESIGN Job 110. 2 -a 11-The tailors Dynam h Drofting the Box for The Tailor's Square consists of along and a short a Un one side of the square there is the smaple mon measure ment and it's denominations the half the quarter were the eighth of an inch. On the other side there are seales e scale measurements. What is near the weather A scale is a system of measuring in the fixed unit is the foundation. ex: On the short arm of the square there we fear In the 16ths the unit of measurement is the of an inch On the long arm of the square there are four scales, z., 12 ths, 6 this, 3 rds, 2 thirds. All units of the scale measurements are measured from the State died miner Study each scale separately some estample: On scale 12 ths, 18=1/2" for Example: On scale 12 ths, 18=3" 5 rds, 18=6" 2 thirds, 18=12" ever mon-scale of the square Uses of the Square. The square is used for measuring and for drawing all horizontal, vertical and angular lines.

Sine " Mais : 21" Ö Back " **3** DRAFTING THE BOX FOR A SKIRT Job Mo. 2.6

WOMEN'S GARMENT DESIGN Job No. 2-6 INSTRUCTIONS Drafting the Box for a Skirt. 1- Draw line from A to B 40" (Front length) 2. At point A square up line to Dabout 18" square up means to draw at right angles, 3-From A to C measure 14 % (12 of waist measure) 5- From D to & square out a line 4 "long 5-From A to F measure 8". The hip line I's 8" 9-From F to G measure 2012" (1/2 of Hip measure) 10-From G to H measure 1/2" (For easing) ii-Draw a line from Ethrough H to I

In Ine from Boto I

Note: There is no allowance for seams.

Garment Design (Homan's) & Mape Like A to E either free hand or with curve stick. rocess- Draft box of strirt as explained in previous lesson. tape mease, tape measure, 45" rala, pencil Mote This diaft has no seam allowances.

For seams in control front or back.

As seam allowance to the front and back ba. 12- From point 2 to point 6 measure 12" " " - - rom point & to point 5 measure 1/2" 9-Draw a line from point & to point 4 7- Point 3 is half may between Band I Marietail about 50" of draffing paren 5- Point I is half may botween A and E 6- From point 1 to point & measure 1/2" 13- Shape line from point 6 to X. TWO-PIECE SKIRT 11-Shape line from point 5 to X 8 Point 4 is I" from point 3. INSTRUCTIONS Jeb 110 J

14-Shape lines from point THREE - PIECE SKIRT WOMEN'S Garment 15- From point 3 to 12 messer 16- " 3 " 13 front. In cutting Note: This has a serve 17-Shape lines from pant allow 1/2" for seam centre book and the in the part, as indica and 13 to 17. 11 to point 6. Tools - Tailor's Square, take monasure, 45" rule, pencil. Materials- About 50" of arafting paper. 12- From point & to 10 measure 1" 13- " " " " " " " " " " 8-From point 6 to 7 measure 6" Draw line from 2 to 6. 9-From point 1 to 8 measure 1/4" 7-From point 5 to 6 measure 10- " 1 " 9 " " -01 6- Drawline from point 1 to 5." Draw line from 3 to 7. 11-Shape lines from 8 to 5 2- From A to Imeasure 3" 3- " 1 " 2 " 4" 4" 4- " 5 " 5" 5- " B " 4 " 6" 1-Draft box of shirt and 9 to 5. point 4 Process

Job No. 4

6 Souls 3/ 1/4 WOMEN'S GARMENT DESIGN Measurements
Waist
Hip
Front Lang Back FIVE-GORE SKIRT N - read me hor. Job No. 5 Back

Tools-Toilors Square, 45 rule, tape measure, shaping lead, seissors, peneil WOMEN'S GARMENT DESIGN

Material- A sheet of drafting paper 50" long.

Process-

1-Draft box of skirt and shape waist and bottom lines.

R-From A to C measure 21/2"

3. " B to D " 5"

4. " C .. A .. 5"

5. " D " F 6- " E·H

7. .. 6. .. 7
8. .. 6. .. 7
9. .. 6. .. 7

10- Shape lines from points Jand

11. From E to L measure 7/8" K to hip line.

12. " E .. M .. 7/8" 13. Shape lines from points

& and M to G

14-From H to Mmessure 34

15- " 4 " 0 " = 3/4"

16- Shape lines from points and O to I

assembling the vorious ports purpose of these is to gaide This pattern has no NOTE: MOKE notch lines as indicated on draft. The the tailor in correctly

Seam allowance, Add 12" to the side of each gore where there is a seam.

WOMEN'S GARMENT DESIGN Measurements Maist front Front Side Back SEVEN-GORE SKIRT Notend. Job Mo. 6 L Fron & 4 Q

Tools-Tailors Square, tape measure, 45 rule, shaping lead, scissors, pencil Material- A sheet of drafting paper 50" long.

Frocess-

1-Draft box of shirt (Ref. Job 2) R-Shope maist and bottom lines of stirt box.

3- From A to Comeasure R'14" 4- " B .. D .. +"

5- : C :: E 7- :: E :: G 8- :: F : H 9- :: C :: I

10 " .. 8/. ..

10- " 6 - 5

11- Shape from points I and

12- From E to K measure 7/8" 13. " E .. L .. I to hip line (dotted)

14-Shap from points Kand L

to hip line (dotted).

15- From Gto M measure 3/4" 16- " G.H " 3/4" 17- Shope from points Mond M to hip line (dotted)

18- Make notches as shown 19- Don't fail to add seam provious job regarding on droft. Rofer to purpose of notches.

allowance to pach gore when cutting pattern.

	measure shaping land seissors, pene	
	6	
	200	
	6	
u	- (5)	
	100	
ı	1.0	
	100	
	1	
ı	21	
	100	
	- 20	100
		7
		1
		60
	4	7
	46	
	5	0
		6
l	0	1
ll		
		4
	3	a
H	5	
and the		of drafting paper 50" long
240	Q	
Total Control		Й
		0
	0	
and section		
G and an		O
I		2.
I		
I		X
ı	Q	A.
H		
I		0
I		
		1
	20	a
H	168	
ı		1
ı	6	6
	- V	9
	Square, 45" rule, tape.	the
	- 51	~
	- 21	
	9	1
		7
	6	
		1
	. Toilor's	
	19	
	16	5
		X
		0
		1
1	5	
		(a)
	Tools-	Materials - A sheet
	0	N
		74

1-Draft box of shirt as explained Process-

10 Job 2.

R-From A to Composure 11/2" J. B. ..

3/2"

: 0% E

13- : C : N

16- From 6 to a moasure The"

17. " G " H

: 91/6

.. 91/2

100

SO. ..

1. 4 . -12


22. Shape the sides of all

the gores from the waist to the hip line.

R3- Notch the gores as

shown on the draft.

R4- Add Spam allowance to each gore.



Tools-Tailor's Square, 45" rule, tape measure, shaping chalk, scissors, peneil. Material. A shoot of drafting paper 50" long.

Process

1- Draft box of shirt as explained

E-From A to C measure 1/2"

The distances from C to E,

E to G, G to I, I to K and

K to M each measure 234"

The distances from D to F, F to H

H to I, I to k and L to K

each measure 51/6"

6-From C to 0 and C to Pomersure distances of 1/12"

7- From E to Q and E to R measure distances of 3/16" each. 8 From G to S and Q to T


measure distances of 3/8" each 9-From I to U and I to V measure distances of 3/8 each

10-From It to W and It to 1 measure distances of 3/8" each.

11- From M to Y and M to I
measure distances of Horach.
12-Shape the sides of all the
gones from the maist to the

13-Natch the gores as indicated on the draft

14-Add soom allowance to each gore when cutting pattern.



Tools - Tailor's Square, 45 rule, tapemeasure, shaping lead, scissors penon Material- A sheet of drafting paper 50" long.

Process-1-Draft box of skirt as explained 17 job 2.

R-From A to Comeasure 114".

3- " B " D " E34"

4-Divide the distance from

C to E into 8 equal parts.

This will give you points J,

H, L, F, P, Mand R.

5-Divide the distance from
D to the back of the skirt
into 8 equal parts. This
will give you points D, K, I,
N, G, Qand S.

6- From C to I and C to R measure distances of 1116" pach. 7- From J to 3 and J to 4

measure distances of 116" each

8-The distances from H to 5,
H to 6, L To 7, L to 8. F 59 F 60

P to 11, P to 12, N to 13, N to 14,
The same They are 14 long

9- Shape the sides of all the gores from the month me

to the hips.

10- Wotch all the gora as on the draft.

11. Add seam allowance to exch gove when cutting pattern.

ONE-FIECE CIRCULAR SMIRT

Job No. II

MOINER'S GARMENT DESIGN

Meusurements
Walst 29"
Malst 40"
Shae 41"
Shae 41"

WOMEN'S GARMENT DESIGN

Tools! Tarior's square Asirule tape measure, shaping lead, mencil scissory Material 50 of drafting paper.

Frocess:

1- From the 5 measure 5" & 2" & 13"

3.- Point D is half way between

+ From D to E measure 1/4

5-Shape waist line from B through E to C

6. - From B to F measure 8"

when cutting the pattern.

Note, Flad soom allowance

7. - Shape line F to G8" below waist line.

8. - From F to G measure 201/2"

(" e of hip measurement) with tape measure.

9- Draw line from C through
10- From B to H measuring C to J 41"
11.- " E " J measuring C to J 41"
12- Shape bottom of STIPE
from H through I to U

WOMEN'S GARMENT DESIGN 10 4 4 4 4 4 W Measurements: TWO-PIECE CIRCULAR SKIRT The second second second second Job No 12

TWO-PIECE CIRCULAR SKIRT

Job No. 12

WOMEN'S GARMENT DESIGN

Tools: Tollor's square 45 rule tape measure shaping lead pencil Material: A sheet of drafting paper, 50" long

Process:

1. - From A to B measure 5".
R. - " B " C " 1412"
(VR of waist measurement)

3- Draw line B to C. 4- Point D is half may between Band C

5- From D to E measure 114" 6- Shape wast line from B through E to C.

7.- From B to F measure 8"
8.- Shape hip line from F to G
8" below waist line BEC
9.- From F to G measure 2012"
(1/2 of hip measurement) with
Tape measurement) with

10. Draw line of back from C through G to J, measuring C to J 41"

11: From & to 11 measiare 40"

13- Shape bottom of shirt from H through I to J.


14. From I to K measure 212" and draw line K to E

15. From E to L and E to M measure distances of 5/8" each.

16.- Shape sides of gones from maist line to hiss (Mana L.)

17.- Allow for seams to each gore when cutting pattern.





WOMEN'S GARMENT DESIGN BACK of a WAIST - SIZE 36 - BUST 38 - SCALE 18

JOB NO. 13

Tools - Tailor's Square, Tape Measure, Pencil, Black Lead, Eraser

MATERIAL - Drafting Paper

PROCESS:

Half of the Size. Size 40, scale 20. Note: In making a draft the scale measure is always one

1-From A to B measure 18-18

151/2" 2- " B " D " 151/2"

81-5/2 4- " C " E

14-18

112", and " D " C " -9

draw B-H at right angles to B-G. 7- From B to I measure 1/8-18

8- " I " J " -6 9- " I " H " 5/8"

10. Point L is half way

11- From L to M measure 21/4", between Fand H.

and draw line from K thru

M to point M.

IR-From K to M measure 5%.

13- " F " O " 13/4" 14- " P " Q " 1" 15- " D " R " 3"

16-Extend line B-G to T

17- " 0-P to S

18-With shoping lead draw


freehand the curves from B to H, from N to L to O,

and from line 0-a to S.

Note: This draft contains 36" seom allowances.

Job No. 14





FRONT of a WAIST SIZE 36. - BUST 38 - SCALE 18

JOB No. 14

WOMEN'S GARMENT DESIGN

TOOL S - Tailor's Square, Tape Measure, Pencil, Black Lead. I aser MATERIAL - Drofting Poper

PROOF SE

1. Draft back of waist as explained in previous job, No. 13, and proceed as follows.

R-Points E, O, P and S are the Same as in previous Job.

3-From E to B measure 114"

4- " C " D " 16-18

5- " D " F " 318"

6- " C " G " Thru G to H.

6- " C " G to m. " | 34" ome

4 com line from D to H measure 5/2"

8- " B " I " 3"

9- " A " L " | 9"

10- " A " L " | 9"

11- From L. to M measure 21/4"

13- Draw line from W thra " 1.

14 From N to a measure 234

15- " D " R " E and draw line from R to a

16- From a to Timeasure 171/2"
17- " P " V " 3/4"

18-With the shaping lead draw the following curves.

(a) - From V to S


(b)-From H + thru I to 0

(c) - From Dinto line R-a

(d) - From Finto Inpo 2-H (e) - From V to T

(4) - From S " "

MIDDY BLOUSE Job Mo 15



3

MIDDY BLOUSE

WOMEN'S GARMENT DESIGN SIZE 36- BUST 38-SCALE 18

Tools - Tailor's Square, Tape Measure, Pencil, Black Lead, Eroser JOTE No. 15

MATERIAL - Drofting Poper

PROCESS:

1. From A to B measure 1/2-18 : 2/ 8

2 " B " C

3/3-18

81-9/

* 80 23

* 10

81-8/

" 2

. 8/E 2 9- " FJ " J

10-Draw line from I thru of to K making I to K, T".

11- From E to L measure 2 34"

13- " 14 " 0 " 25/8" 15- " 14 " 14 " -21

15- Draw line from 0 thru P to Q, e N 14 " A " B " **

making o to a 7" long

16- From Cto R MEOSUMO 19"

17- From R to Smeasure 4 34

· -02

* - ZZ

- E 2

1 4

25- " C " d

27- With the shaping lead draw

(d) From h to V (g) ... g thru a to Z freehand the following lines. (4) From B to T

SLEEVE / MIDDY

MOMEN'S GARMENT DESIGN



close Ma 16

SLEEVE MODY

SIZE 36

JOB No. 16

WOMEN'S GARMENT DESIGN Tools - Tailor's Square, Tape Measure, Pencil. Black Lead, Eroser

MATERIAL - Drofting Paper

PROCESS:

1. From A to B measure 3" R. " B " C

3- Draw vertical lines at points A, Band C.

4-From B to D measure 91/2"

S 34. 5. " C " E "


6- Draw line connecting points Dand E

at least 10" space below 7- Make another draft of this sleeve and allow 1100 A-B-C

8-When draft is completed fold paper on line A-B-C.

on folded paper, starting 9- Cut out sleeve pattern around to D, to E, to at point A and going C and back to A.

muslin, sew it and try it on the tailor's form. cut a fitting of drilling 10- Mote: It is advisable to cloth or unbleached



TOOLS - Tailor's Square, Tape Measure, Pencil, Black Load, Eraser

MATERIAL - Drafting Paper PROCESS:

Diagram A

Sailor Collars:

1- Put front and back of waist pattern together as shown by dotted lines in this diagram and outiline.

2- From a to dimeasure 6"

3- " die " e " 7"

4- " a. " b " 9"

freehand the lines from

6- With shoping lead draw

2/4

f to b, and from e to f

Diagam B

Round Collar:
1-Outline front and back
of waist as illustrated
in this diagram.

From j to K measure 3.

3. " h " i " " 5"

4-With the shaping lead
shape curred line the
three inches below the
curred line by

ONE-PIECE OLFEVE

SIZE 36 - SCALE 18

WOMEN'S GARMENT DESIGN

JOB No. 18

TOOLS - Taylor's Square, Tape Measure, Pencil, Black Lead, Eraser

MATERIAL - Drofting Paper

PROGESS

1- From A to B measure 16-18 161 R. . . B .. C .,

3- Draw vertical lines at

points A, B and C.

4-From A to Dimeasure 43-18 5- " D " E " 11/4"

6-Point His one half of

A.E. Draw H to I

7- Draw lines I to E and I to A 8- From B to I measure R"

9- " J" " 11/4"

4 /2:

of sleeve freehand from 12- With shaping load draw top point B thru 14 thru

4, thru H, thru M to F

13- From C to M measure 11/4"

14- " G " O " 23/4" 15- " O " P " /"


16- With shaping lead


draw curred lines from Bto IN and F to P.

Control of the last

JOB No. 19

WOMEN'S GARMENT DESIGN ONE-PIECE SLEEVE Roint at Bottom





WOMEN'S GARMENT DESIGN OME-PIECE DIEEVE SIZE 36 SCALE 18 JOD No. 19

TOOLS - Tollor's Square Tape Measure, Penall. Black Lead, Eraser

MINIBRIAL - Drofting Paper

PROCESS:

1 From A to B measure 514". . 9/ * * P .. C . 2 3- .. B. D

4- Draw vertical lines at points R. B, C and D.

5 From A to E measure 814" 6- Draw line E-H parallel to Me A-D

8 From E to J measure 318" 6 " H " 134". 7 Drow 1100 B to E

shaping lead line A-J-F 4- Draw freehand with and line A-K-1

12-From G to H measure 11/2"

13- " H " M " 11/4" 14- " D " M " R"

from F to L, L to M, 15- Draw straight lines and M to W 16-With shoping lead chow lines from F to L to My freehand the curred





Women's GARMEN'T Deston SIZE 36 - SICALLE 18 TWO-PIECE SLEEVE JOB (No. 20

TOOLS - Tailor's Square, Tope Measure, Pencil, Black Lead, Croser

MATERIAL - Drofting Popula

PROGESS:

J-From A to B measure #-18 B . C

in the second 36

がり

8-Drow Wertical lines D.1

and C-J.

and array line from E to H 9. From of to 1 measure 10.

11-From L to M measure 4/4" 10-Draw vertical line F to L

1816

15- Draw Mines from M to D 19 0

16- From D to a measure of

10 ... of

: 80

8/6


19- Draw lines from Q to F h = EL-Extend line ON 14" to 20- From Q to Q measure ye

RR. From N to N + measure 36 23- Shape armhale from IV to the right.

24- With the shaping was Qr with shaping land draw lines QRS and

JOB NO. 21

WOMEN'S GARMENT DESIGN TWO-PIECE SLEEVE



WOMEN'S GARMENT DESIGN SIZE 36-SCALE 18 TWO-PIECE OLEEVE Top Part JOB Mo. 21

TOOLS - Tailor's Square, Tape Measure, Pencil, Block Lead, Eraser

MATERIAL - Drafting Poper

PROCESS:

1-Make a draft of the undersleeve as explained in the previous lesson, Job 20.

R. Letter each point.

4- Draw lines Choa and a to F 6- " PE " B " 13/4" 5- From I to il measure "12" 3- From E to a measure 114"

" e/// F " C " C " I'la"
8-Draw lines a to b and b 7- " 5 " 0 C P 9. From D to e measure 11/4" 10- " A " B " A " -11

shaping lead the following 12- Draw freehand with the

(a)-From C to e, to f, touching line A.H. to g. to d

(b)-From C to a to F (c) - " d " b " c 13-Make a second draft of your teacher to show this pattern and ask you how it is cut and motched.


JOINION CO

JOB MO. R.R.

ONE-PIECE SLEEVE Dart at Bottom

For Waist

WOMEN'S GARMENT DESIGN



SIZE 36 SCAME 18 ONE-PIECE SLEEVE

WOMEN'S GARMENT DESIGN

TOOLS - Tailor's Square, Tope Measure, Pencil, Black Lead, Erose MATERIAL - Drafting Poper JOB No 22

PROCESS:

1. From A to B measure 14-18

2- " B " C " 91/2" 3- " B " D " 191/2" 4- " A " I " 81/4"

6- Draw lines A to J and E to J

7- From A to I measure 23/4"

8. " F. " 6" 9. " F. " 3/8" 10. " F. " 3/8" 11. " X " 0 " 2/8" 12. " X " Y " 3/8"

" #/ B

13- With the shaping lead

draw freehand the line from B thru Y, I, L, M, O, to P

14- From Cto R measure 10"

15- " R " T "

16- Draw lines T to D and T & H

17- From R to 3 measure 3"


RI - Draw lines B.Q. Q.V., and W. J

22-From G to U measure 18

23- " H " X " " 38 24- " X " Y + M 25- Draw lines F to U, U to X

and Y to S.

26- With the shaping lead curve from F To U to X draw freehand the



COAT DRESS

JOB No. 23

WOMEN'S GARMENT DESIGN

Size 36 - Bust 38

TOOLS - Tailor's Square, Tope Measure, Pencil, Black Lead, Eraser MATERIAL - Drofting Poper

PROCESS:

Draw a horizontal line A to B 41" long

2- Place the back of the waist pattern so that the centre back will be on A-C, and outline it.

5-Mank points E, F, Dand C. 4-From D to Gmeasure 314" 5-Draw line from F thru G to H, 32" long 6-From E to a measure 114" 7- " F " b " 4"

Draw a horizontal line

A to B 38" long

2- Place the front of the

point C will be 114 below

D, and outtline the front.

3-Mark points A, C, D, E, H and G.

E to F 32" long

5- From G to b measure 114"

6- " E " a " A"

7- " A " c " A"

8- Shape dot and dash lines
from b to a and d to c

This is for a guimpe.

a to b. This is for a sumpe


8- Shape dot and dash line from

4-Extend line EH to F making

4. Glickstolo



For World on Dress



WOMEN'S GARMENT DESIGN SIZE 36 - BUST 38 - SCALE18 D I I I I I I DOOR X JOB No. 24

Tools - Tailor's Square, Tape Measure, Poncil. Black Lead, Eraser

MATERIAL - Drafting Paper

PROCESS.

1. From A to B measure 18-18 , #/. L S . B . C

B. D

15/2"

2/2-18

14-18

81-8/

: 2/

: 8//

way between Fand H 10-Locate point L half

12- Draw line from K thru M 11- From L to M measure 214"

14- " E . O . " -+1 13- From K to M measure 54

15- " P " Q "

16. With the shoping read draw freehand the curves from


B to I and from 14 to O. 17- Cut out a full size

pattern and but on the tailor's form.



WOMEN'S GARMENT DESIGN





WOMEN'S GARMENT DESIGN SIZE 36 - BUST 38 - SCALE 18 LINING Front JOB No. 25

[OOLS - Toilor's Square, Tape Measure, Poncil, Black Lead, Fraser

MATERIAL - Drafting Paper

PROCESS:

1-Draft back of lining as explained in previous job (#24)
2-Mark points E, O, Pand a.
3-From E to B measure 1/4"
4- " C " D " | 16-18
6- " C " G " | 3/8"
7- Draw line from D thru G to d
(From D to d 5/4")

8-From P to H measure 3/4"
9- " a " I " 19"
10- " I " J " 2"
11-Draw JH at right angles to J-H
12-From K to 4 measure 11/4"
13-Dram line through points 4
and of extending it to the

10/12

1: 5

R4- "

が内


7 " 8 " 6

21- From J to S measure 4" 22- " O " T " 31/2" 3/2"

· 8//

1.143

14- From L to M measure 114".
15- " of " N " " S".
16- " N " Q " 114.
17- " M " R " " I'/4".
19- Draw line R Q and shape H & R.
RO-With shaping lead draw
curve from D the H to O



TOOLS - Toilor's Square, Tape Measure, Pencil, Black Lead, Eraser MATERIAL - Drafting Paper

PROCESS

1. Draw the horizontal line 14-H 7- From A to B measure 20" R-In the middle of your paper near the bottom of your paper. draw the vertical line Idst and dash line J H-B.

3- Place the front and back of the waist pattern on line H-M and outline them as indicated by dotted lines.

6-With shaping lead draw freehand the line of the 4-From E to F measure 114" "/ " Q " 2 " -S neck from F-D

8- " B " I " " 8" " 9- " 6" " 10- " L " M " 31/2"

10- " L " M

12- With shaping lead draw lines from H to M and


M to I

13-Fold paper on line A-B and cut pattern on lines F-H, H-Mand 14-1

14-Unfold paper and your and P-14.

WOMEN'S GARMENT DESIGN Box COAT





BOX COAT Back

SIZE 36-BUST 38-SCALE 18

WOMEN'S GARMENT DESIGN

JOB No. 27

Tools - Tailor's Square, Tape Measure, Pencil, Block Lead, Eraser MATERIAL - Drafting Poper

PROCESS:

From A to B measure 18-18

1/4-18

2/3-118

: 25

15

8- Draw line B-1 at right angles to B-H

9- From B to L measure 18-18

10- " L " M

12. Point I is half way between Gond I


13- From I to K measure 214"

14- " F " O "

15-Draw line 0-P at right angles to line C-F

17- Drow line from 0 through 16- From P to a measure 1"

18. From R to Smeasure I"



WOMEN'S GARMENT DESIGN BOX COAT SIZE 36-BUST 38-SCALE 18 JOB MO. 28

Tools - Tailor's Square, Tape Measure, Pencil, Black Lead, Eraser

MATERIAL - Drafting Paper

PROCESS:

1- Draft back of box coat as explained in previous lesson R. Mark off points F.O. P

and S

3. From P to A measure 1" 4- Make line O-B equal to

5 From F to Consure 13/4" line G.S.

6- " D " E " 13-18 7- " E " F " 3/4" 8- " F I " G " 3/8"

9- " D " H " 134"

10-Draw line from Frthru H to I, 5" long.

11-From F to Imagsure 8"

12- Draw line from 6 thrust 14-From K to Lineasure 19"

15- " L " M " " 2" 16- " M " N " " 2"4" 17- " Q " F " " 1/2"

18- With shaping lead anaw freehand the curves

at the peck, shoulders, armhole and bottom.

WOMEN'S GARMENT DESIGN



JOB No. 29

WOMEN'S GARMENT DESKIN

Tools - Tailor's Square, Tope Measure, Pencil, Block Lead, Iraser MATERIAL - Drafting Paper

PROCESS:

1-Make a droft of a coat as explained in previous lessons

R-From A to Boneasure II"

3- " C " D " 3/4"

4- Draw line from B thru
C about 20" long

from C and 114" from


6-Draw a straight line from E to the neck 7-Draw line E-G at might angles to E-C.

8-From F to G measure 21/4" 9. " J .. H .. 23/4"

9- " J " H " " B

11- Draw Thoe H to I R. I long and at an angle of 45° to A-H.

12. It is advisable to cut out collar of drilling cloth or muslin and som it into the body of the coat.



SHAWL COLLAR

JOB No. 30

WOMEN'S GARMENT DESIGN

TOOLS Tailor's Square, Tape Measure, Poncil, Black Lead, Eraser MATERIAL - Drafting Poper

PROCESS:

1- Draft coat as explained in previous lessons.

E. From A to B measure II"

3- " C " D " 3/4"

4. Draw a line from B thru
D To F Pobout 19".

5. Locate point E 3"

from c and 144" from

6- Draw line from E to curve of neck

7- Draw line E-G at right angles to line E-C.

8-From F to G measure 214" q. Draw line G-I-J parallel


to Shape line from I to B.

JOB No. 31

WOMEN'S GARMENT DESIGN TWO-PIECE SLEEVE

For Coat


Size 36



shape the curves T to S. 15. From E to P measure 6" 16- " N " Q " 51/2" 17- " O " P " 4" 18- " P " S " 3/8" 20- With the shaping lead 3 JAK: 14-Draw straight lines from 11- From B to M measure 34" 12. " C " M " 134" WOMEN'S GARMENT DESIGN ru N TOOLS - Tailors Square, Tape Measure, Pencil, Black Lead, Eraser M-14-0, and P-Q-R. M to 14 and 14 to C JOB MO. 31 FOR COAT PART WOMEN'S GARMENT D 0 " 0 " - 6/ 1- From A to B measure 1/3-18 7- Draw lives F-G, B-H and 1/3-18 10 Draw lines from C to I 1/4" C 9- " J " K " 4/2" 13-18 8-From H to Imeasure 10" 8. " B .: 6 .. 9" 181 MATERIAL - Drafting Paper and from D to H A W B B J: 7 : -9 D-C PROCESS:

JOB No. 32

WOMEN'S GARMENT DESIGN TWO-PIECE SLEEVE TOP Part Size 36 For Coat



TOOLS - Tailor's Square, Tape Measure, Pencil, Black Lead, Erasen MATERIAL - Drafting Paper

PROCESS:

Proft box and under part of sleeve as explained in previous Jesson.

R. Mark points A, B, C, D, E, F, G, H, I, J, Kand L 3-Draw line A to H 4- Draw line B to F

5- From C to a measure 114"
6- Draw lives from B to a to D
7- From G to b measure 1/2"
8- " b " c " z"

9. " a " d " 8/4" 10- " D " e " 6" 11- Drow straight lines from

e to d to e.

12. From E to f measure 1/4"

13- " A" S " 3" 14- " F " h " 3"

15- " h " d " 11/4"

16-With shaping lead draw freehand the following curves:

(a) B-fg-i-c

(b) B-f-g-4-h-b


Curre a represents a wider top sleeve and out

JOB No. 33

RAGLAN

Size 36

WOMEN'S GARMENT DESIGN



SCALE 18 WOMEN'S GARMENT DESIGN

TOOLS - Tailor's Square, Tape Measure, Pencif, Black Lead, Eroser MATERIAL - Drofting Poper

PROCESS:

1- Draw box coat as explained In previous lessons R-Draw line B to C.

3- From B to D measure 214" 4- " F " F " 11/2"

5- 1 G . H

6- Draw straight line

from I to H


7- With shaping lead draw A through D through freehand curre from F to O.

from I through H to J. 8- With shaping lead draw freehand the curre

9- Submit your draft to Instruction in culting correction and for your teacher for this pallern

JOB No. 34

RAGLAN SLEEVE Under Part Women's Garment Design Size 36



WOMEN'S GARMENT DESIGN KAGLAN SLEEVE Under Part

SIZE 36-SCALE 18

JOB No. 34

TOOLS - Tailor's Square, Tope Measure, Pencil, Black Lead, Eraser MATERIAL - Drafting Poper

PROCESS:

1-From A to B measure 16-18

2- " B " D " 9"

1/3-1/8

6- Draw lines B-G, C+H, D-I

7- From I to I measure 4" 8- Draw line from D to J.

9- From B to H measure 1/8"

10- " 6 " 134"

1/2:

5/2: N : 7 : 1

L to M and from E through 14 - Draw lines from It through 4/2: 13- " N " O

15. From E to R measure 3/8"

16- " N " 3 " -31

17- " C" P " 1/2"

18- Draw lines from B to Pto D 19-From 0 to a measure 2"

21- With shaping lead draw freehand the following 20- Draw line from H to a

CUMVES.


(a) B-P-D

M-4-M

(c) E-N-O

(d) E-H-Q

RAGLAN SLEEVE TOP Part WOMEN'S GARMENT DESIGN Size 36



RAGLAN SLEEVE

SIZE 36 SCALE 18

WOMEN'S GARMENT DESIGN Top Part JOB NO. 35

TOOLS - Toilor's Square, Tope Measure, Pencil, Black Lead, Eraser MATERIAL- Drafting Paper PROCESS:

added to the draft made 1- The following is to be in the previous lesson

R-From A to Timeasure 16-18

3- " T" " T" " 11/4"

13-18 10 1 .. 2 .. -4

"8//

N : N

1 : Q

: W/

81-8/

14:

11- Draw line from b to B

12-Point c is half way between B and b. 13-From c to d measure 1/2"

14- " Z " 6 " /12-18

15. " e" f " 3/4"

16- Draw a straight line from f to F.

17- With shaping lead draw freehand the curres as follows:

(c) e-W-V (4) b-d-B

J-f (b) (b) a-X-V

1001.S - Toulor's Square, Tope Measure, Pencil, Black Lead, Eroser MATERIAL - Drofting Poper

PROCE 38

1 Draw line AB 32 long

a Place back of box coat

on line A-B and drow

= Wart points C. D. E.F

- From D. To H measure 112-

o Diraw line from C through of to I, making C to I

Just 1000

angles to the S.C.

9/10 N - J

o Draw Mar of to A

11- Draw line E to G

rz- With shoping lead draw freehand the curre

under the ormhole

WOMEN'S GARMENT DESIGN W₁ BUTTERFLY JOB No. 37

FRONT BUTTERFLY

JOB No. 37

WOMEN'S GARMENT DESIGN

TOOLS - Toilor's Square, Tape Measure, Pencil, Black Lead, Eraser MATERIAL - Drofting Poper

PROCESS:

it. Refer to previous butterfly and outline 106.

R. Mark points A, B, H, J, I and F

3- Line H-4 is 1/2" from 1-7 acil 4- How take front pattern of box coat and place the diapram indicates it on your draft as by dotted lines

1- Take pattern of back of 5- This will give you points F, G, M, M, C, D and E


6- The heavy lines indicate pattern of the butterfly. the outline of the front

SEMI FITTING COAT


JOB Mo. 38

Size 36

WOMEN'S GARMENT DESIGN



9- With shaping lead draw freshand 20- Draw lines from Pto a to To to T, and from I to S. 9-Draw line B-J at right angles to line B-1 4 Draw lines Pto Q, Q to V and V to W The curres U-a, Q-R, Z-a, B-M, WOMEN'S GARMENT DESIGN Tools - Tallor's Square, Tope Measume, Penal, Black Lead, Eraser 1/2// 8 Dran lines from X to Z to b I-From P to U megsure 3/8" 5- From F to X measure Va" 17- From I to R measure 4" R " V " 3- " T" W. " FRENCH BACK Part I M-0 and O-X N = X = 4 7. " 4 . 6 16 " E" S SEMI-FITTING COAT Size 36 BUST 38 SCALE 18 M. T. O. M. O. M. O. S. W. P. W. J. W. W. J. W. W. J. W. W. J. W. W. J. W. W. J. W. W. J. W. W. J. W. =- Point I is one half of HEJ. 1- From A to B measure 1/8-1/8 W-From B to IT measure 18-18 10 - 10 M 4 M. Frank L to P measure 3" ,50 ů. 200 · * MITTERIAL - Drofting Paper Mark ... B·C JOB No. 38 A: A PROCESS:



WOMEN'S GARMENT DESIGN FRENCH FRONT SIZE 36 BUST 38 JOB No. 39

TOOLS - Tailor's Square, Tope Measure, Pencil, Black Lead, Eraser

MATERIAL - Drafting Paper PROCESS:

1- Draft back as in Job No. 38

3-From F to A measure 1/2" R. Mark points F, Y and a.

3/4" 28/11 4- " Y " B "

14-18

114:

18

3/8

11- Draw line H thru of to H moving

12-From M to M measure 12"

3 3/4"

17- Drow has from O thru 7 = Lettorn (S) 18 - From G 1 V reposure ?" wa wan

19-From R to W measure 6"

RO- " A " X

24-Draw lines from I to 6 and from I to 6 and

25-From W to d measure 4" and are from V to e measure 3%.

28 - Draw lines from e and f to d 29- From S to & measure 3 34"

30- " & " h " 3"

31- Draw lines from & to e and h to f.











